

**Initial Resistance @ 300 FPM (in. w.g.)**

<b>Size</b>	<b>Fiberglass</b>	<b>Polyester</b>	<b>Carton Quatity</b>
8 x 16 x 1	0.07	0.15	12
10 x 10 x 1	0.07	0.15	12
10 x 20 x 1	0.07	0.15	12
12 x 20 x 1	0.07	0.15	12
12 x 24 x 1	0.07	0.15	12
12 x 25 x 1	0.07	0.15	12
14 x 20 x 1	0.07	0.15	12
14 x 25 x 1	0.07	0.15	12
15 x 20 x 1	0.07	0.15	12
16 x 16 x 1	0.07	0.15	12
16 x 20 x 1	0.07	0.15	12
16 x 22 1/4 x 1	0.07	0.15	12
16 x 25 x 1	0.07	0.15	12
18 x 24 x 1	0.07	0.15	12
18 x 25 x 1	0.07	0.15	12
20 x 20 x 1	0.07	0.15	12
20 x 24 x 1	0.07	0.15	12
20 x 25 x 1	0.07	0.15	12
22 x 22 x 1	0.07	0.15	12
24 x 24 x 1	0.07	0.15	12
25 x 25 x 1	0.07	0.15	12

**Initial Resistance @ 300 FPM (in. w.g.)**

<b>Size</b>	<b>Fiberglass</b>	<b>Polyester</b>	<b>Carton Quantity</b>
12 x 24 x 2	0.09	0.19	12
14 x 20 x 2	0.09	0.19	12
14 x 25 x 2	0.09	0.19	12
15 x 20 x 2	0.09	0.19	12
16 x 20 x 2	0.09	0.19	12
16 x 24 x 2	0.09	0.19	12
16 x 25 x 2	0.09	0.19	12
18 x 24 x 2	0.09	0.19	12
18 x 25 x 2	0.09	0.19	12
20 x 20 x 2	0.09	0.19	12
20 x 24 x 2	0.09	0.19	12
20 x 25 x 2	0.09	0.19	12
24 x 24 x 2	0.09	0.19	12
25 x 25 x 2	0.09	0.19	12