PRODUCT INFORMATION PACKET

Model No: D1103 Catalog No: D1103 OEM Replacement Motor, 1/20 HP, 1 Ph, 60 Hz, 208-230 V, 1500/1300 RPM, 1 Speed, 3.3" Diameter, OAO



Regal and Fasco are trademarks of Regal Rexnord Corporation or one of its affiliated companies. ©2023 Regal Rexnord Corporation, All Rights Reserved. MC017097E





Product Information Packet: Model No: D1103, Catalog No:D1103 OEM Replacement Motor, 1/20 HP, 1 Ph, 60 Hz, 208-230 V, 1500/1300 RPM, 1 Speed, 3.3" Diameter, OAO

FASCO

Nameplate Specifications


Phase	1	Output HP	1/20 Нр
Output KW	0.04 kW	Voltage	208-230 V
Speed	1500/1300 rpm	Frame	3.3
Enclosure	Open Air Over	Thermal Protection	Thermally Protected
Efficiency	31 %	Ambient Temperature	40 °C
Frequency	60 Hz	Current	1.15/1.35 A
Duty	Air Over	Insulation Class	В
UL	Recognized	CSA	Y
CE	Ν	Number of Speeds	1

Technical Specifications

Electrical Type	Shaded Pole	Starting Method	Across The Line
Poles	4	Rotation Counterclockwise Shaft End	
Mounting	Extended Studs	Drive End Bearing	Sleeve
Opp Drive End Bearing	Sleeve	Frame Material	Steel
Shaft Type	Flat	Overall Length	5.58 in
Frame Length	2.82 in	Shaft Diameter	0.313 in
Shaft Extension	2.25 in		
Connection Drawing	NA	Outline Drawing	71634346

This is an uncontrolled document once printed or downloaded and is subject to change without notice. Date Created:11/14/2023





В

ed Copy 4		3		
NOTES: 1. STAKE STATOR TO MAIN FRAME PER 88830264. 2. MAXIMUM TORQUE REQUIRED TO TURN MOTOR SHAFT IS 3. MAKE-UP WASHERS ARE TO BE ADDED OR DELETED TO 7 4. LEAD RIP ON FASCO END MUST NOT EXTEND OUTSIDE O	S 3/8 INCH-OUNCE. ACHIEVE REQUIRED ENDPLAY. F MAIN FRAME.			
			FRONT END	

PACKING SPECIFICATIONS

PACK 1 PER CARTON, 45 CARTONS PER LAYER. 6 LAYERS PER PALLET, 270 MAX. PER PALLET. PACK PER 88834200. 1.

PALLET, 270 MAX. PER FALLET. FACK FER 60034200. PLACE FOAM RING ON BACK END OF MOTOR. PLACE FILLER TUBE OVER SHAFT EXTENSION AND PLACE IN CARTON SHAFT UP. PLACE (4) NUTS IN PLASTIC BAG AND PLACE (1) BAG IN EACH CARTON. 2.

(4) NOTS IN PLASTIC BAG AND PLACE (1) BAG IN EACH CARTON. CLOSE FLAPS AND TAPE. PLACE CARTON LABEL ON SHAFT END OF CARTON. CARTON LABELS MUST ALL FACE ONE DIRECTION TOWARD OPEN END OF THE 3. PALLET. PER 88834408.

PLACE ONE FLAT PAD ON PALLET, PLACE ONE FLAT PAD BETWEEN 4. EACH LAYER AND ONE ON TOP. PLACE ALL INSPECTION STICKERS AND WRITING ON TOP OF FLAT PAD.

4

